

From: [Phillip Winsor](#)
To: [Moore, Gary](#)
Subject: RE: Falcon Refinery
Date: Tuesday, July 09, 2013 8:06:43 AM

Gary;
Here's the web link for the TRRP guidance documents.

www.tceq.texas.gov/remediation/trrp/trrprule.html

You will see the TPH guidance and all the other guidance documents in the TRRP program.

Phillip Winsor, PE
Superfund Section
Remediation Division
TCEQ
Office Phone # (512)239-1054
Facsimile: (512) 239-2450
e-mail: Phillip.Winsor@tceq.texas.gov

From: Moore, Gary [<mailto:Moore.Gary@epa.gov>]
Sent: Monday, July 08, 2013 8:21 PM
To: Phillip Winsor
Subject: Falcon Refinery

Phil:

I need to find out what the cleanup levels would be for a release below the tank bottoms. Since these tanks contained crude oil, I would assume that it would be TPH.

How does TCEQ handle cleanups under tanks that are to be refurbished and put back into use?

Thanks
Gary Moore
Federal On-Scene Coordinator
U.S. EPA Region 6
214-789-1627 cell
214-665-6609 office
moore.gary@epa.gov



9568227